


KODAK RELIABLE IMAGE TIP # 23

Process Control Reminders

Calibrate your densitometer weekly with densitometer manufacturer's strip



Use the Kodak correlation strip weekly to verify continuity


KODAK QUALITY CONTROL DENSITOMETER CORRELATION STRIP

DENSITOMETER: _____

D-MAX	REFERENCE STEP	D-MIN
2.02	1.07	.03
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

TECHNICIAN: Dana Griffin DATE: 12/31/98

Use at least **three** process control strips for each test and plot the average densities for D-Min, D-Max & AIM



Plot your test results daily

